

## Reproduction Expendable Supply Set, Moist Process

SC: 3610-97-E18  
NSN: 3610-00-889-3246

### System Description

Provides a capability to produce engineering drawings and prints in the field.

**This system is not currently in reset.**

### Reset Type

**Reset Work (Field Level)** - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

### Reset Strategy

n/a

### Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

### Reset Responsibility

**Unit**

### Reset Location

This system is not currently in reset.

### **- Contact Information -**

877.4.PMSKOT (877.476.7568)  
[rock-pm-skot@conus.army.mil](mailto:rock-pm-skot@conus.army.mil)